

TABLE OF CONTENTS

INTRODUCTION

1.1 GOAL AND OBJECTIVES	1-1
Goal.....	1-1
Objectives	1-1
Limitations	1-1
Disclaimer	1-2
1.2 LOCATION	1-2
Aerial Photography	1-4
1.3 LOCAL COMMUNITY ORGANIZATIONS	1-4
1.4 ACCESS TO PRIVATE PROPERTY	1-5
1.5 LONG TERM, AGENCY-COMMUNITY RELATIONSHIPS	1-5

REGIONAL SETTING

2.1 GENERAL STATEMENT	2-1
2.2 PHYSIOGRAPHY	2-1
2.3 CLIMATE.....	2-1
2.4 VEGETATION.....	2-2
2.5 GEOLOGY AND SOILS	2-2
2.6 LAND USE.....	2-3
Road and Stream Corridor Interactions	2-6
2.7 SALMONID HABITAT	2-8

GEOLOGY AND GEOMORPHOLOGY

3.1 GENERAL STATEMENT	3-1
3.2 PREVIOUS WORKS	3-1
3.3 LITHOLOGY AND STRATIGRAPHY	3-1
Bedrock Units in the La Honda Watershed	3-1
Bedrock Units in the La Honda Creek Channel.....	3-3
Surficial Units in La Honda Creek.....	3-4
3.4 SOILS IN THE LA HONDA WATERSHED	3-7
Soil Qualities.....	3-8
3.5 STRUCTURE AND SEISMICITY	3-9
Faults.....	3-9
Folds.....	3-11
3.6 LANDSLIDES AND SLOPE EROSION.....	3-11
Paleo Mega-landslides	3-12
Transition to Present Processes.....	3-12
Gully Erosion.....	3-12
Recent and Active Landsliding.....	3-12
Material Susceptibility to Failure.....	3-13
Triggering Mechanisms	3-14
3.7 FLUVIAL GEOMORPHOLOGY	3-17
General Statement.....	3-17
Bank Erosion.....	3-19

Knickpoints	3-22
Aggradation vs. Degradation of the La Honda Creek Channel	3-23

HYDROLOGY

4.1 GENERAL STATEMENT	4-1
4.2 PRECIPITATION	4-1
Annual Rainfall for La Honda Creek	4-1
Seasonal Rainfall	4-3
Daily Rainfall	4-4
Hourly Rainfall and Rainfall Intensity	4-5
4.3 DISCHARGE	4-6
La Honda Creek Estimated Runoff Magnitude-frequency Relationships	4-6
Measuring Discharge, La Honda Creek	4-8
4.4 WATER TEMPERATURE	4-15
4.5 TURBIDITY	4-18
4.6 CONCLUSIONS	4-23

MACROINVERTEBRATE BIOLOGY

5.1 GENERAL STATEMENT	5-1
5.2 INTRODUCTION	5-1
5.3 METHODS	5-2
Field Methods	5-2
Benthic Macroinvertebrate (BMI) Laboratory Analysis	5-3
Data Analysis	5-3
Index of Biological Integrity (IBI)	5-4
Physical Habitat Quality	5-6
5.4 RESULTS	5-6
BMI Community Structure	5-6
IBI Scores	5-12
Physical Habitat Quality	5-13
5.5 DISCUSSION	5-13
5.6 CONCLUSIONS	5-14

ANADROMOUS FISH HABITAT

6.1 GENERAL STATEMENT	6-1
6.2 PRIOR STREAM SURVEYS	6-1
6.3 SURVEY DESIGN	6-4
6.4 SURVEY OF PHYSICAL CHARACTERISTICS	6-8
Channel Cross-sections	6-8
Channel Slope	6-10
Bank Characteristics and Riparian Vegetation	6-11
Sediment Bars and Other Deposits	6-13
Sediment Grain Size Analysis	6-19
Pools	6-28
Large Woody Debris	6-33
The La Honda Creek Channel	6-37

6.5 SALMONID SPAWNING HABITAT	6-37
Spawning Habitat in La Honda Creek	6-38
6.6 SALMONID REARING HABITAT	6-42
Salmonid Rearing Habitat in La Honda Creek	6-43
6.7 CONCLUSIONS.....	6-45

ENGINEERING CONSIDERATIONS

7.1 GENERAL STATEMENT	7-1
7.2 LANDSLIDING	7-1
Excess Water.....	7-1
Removal of the Toe.....	7-2
7.3 ACCELERATED BANK EROSION	7-3
Channel Realignment (Straightening).....	7-3
Bank Protection (Hardening) Structures	7-3
Structural Encroachment.....	7-7
7.4 STREAM INCISION.....	7-8
7.5 FINE SEDIMENT CONTAMINATION	7-9
Breakdown of Mudstone.....	7-9
Entrainment of Soil Ravel.....	7-10
Input from Tributaries.....	7-10
Drainage from Highway 84	7-11
7.6 PRESSURE POINTS.....	7-12
Landslide Bend Pressure Point	7-12
Riprap Bend Pressure Point	7-18
Sackrete Bend Pressure Point	7-22
Apple Jack’s Bend Pressure Point	7-27
Green House Bend Pressure Point.....	7-30
30 MPH Bend Pressure Point	7-33
7.7 MONITORING.....	7-37
Cross Sections.....	7-37
Bank Pins	7-37
Riprap Markers	7-38
7.8 CONCLUSIONS.....	7-38

RECOMMENDATIONS

8.1 RECOMMENDATIONS FOR FUTURE WORK	8-1
---	-----

REFERENCES.....	9-1
------------------------	------------

APPENDICES

A. Land use history	A-1
----------------------------------	------------

B.	Tor vane shear strength values	A-5
C.	Precipitation data	A-9
D.	Discharge data for San Gregorio Creek	A-10
E.	Discharge data for La Honda Creek	A-11
F.	La Honda Creek water and air temperature data	A-22
G.	Macroinvertebrate data	A-24
H.	Previous CDFG observational stream surveys	A-36
I.	Longitudinal profile data	A-42
J.	Sample reach cross-section data	A-43
K.	Bankfull channel width and depth data	A-49
L.	Sample reach slope data	A-50
M.	Sample reach bank condition data	A-52
N.	Sample reach riparian condition data	A-56
O.	Sediment deposit data	A-61
P.	Surface grain size data	A-66
Q.	Subsurface bulk grain size data	A-75
R.	Pool data	A-77
S.	Large woody debris (LWD) data	A-79
T.	Bank pin and rip rap marker data	A-91
U.	Pressure point cross-section data	A-93
V.	Sample reach bank erosion data	A-96
W.	Geologic time scale	A-100
X.	Unified Rock Classification System	A-101
Y.	Modified Mercalli Intensity (MMI) scale based on observations of effects during earthquakes	A-102
Z.	Daily rainfall.	A-103
AA.	San Gregorio Creek annual runoff, seasonal runoff character, and runoff magnitude-frequency relationships.	A-104

LIST OF FIGURES

Figure 1-1. Location of the La Honda Creek watershed, San Mateo County, California.	1-3
Figure 1-2. Map of the San Gregorio and La Honda watersheds.	1-3
Figure 1-3. Creek access in the La Honda Creek study area.	1-6
Figure 2-1. Geologic map of the La Honda Creek watershed.	2-4
Figure 2-2. Topographic maps of the study area.	2-5
Figure 2-3. Delta of fine sediment beneath a culvert draining Highway 84.	2-6
Figure 3-1. Geological map of the La Honda Creek study area.	3-2
Figure 3-2. Tertiary Sedimentary Rock map unit in bank of La Honda Creek.	3-6
Figure 3-3. Colluvium map unit exposed by landslide, La Honda Creek channel.	3-6
Figure 3-4. Contact showing relationship between Basalt, Terrace deposits, and Colluvium map units.	3-7
Figure 3-5. Measures used to reduce infiltration into the "Blue tarp landslide".	3-15
Figure 3-6. Hanging tributary at Woodhams Creek.	3-18
Figure 3-7. Sediment winnowed from debris flow entering channel.	3-18
Figure 3-8. Failing portion of sackrete bank revetment.	3-20
Figure 3-9. Total volume of measured bank erosion.	3-20
Figure 3-10. Average bank erosion per unit channel length.	3-21
Figure 3-11. Age estimates associated with measured erosion.	3-21
Figure 3-12. Average rate of lateral bank erosion.	3-22
Figure 3-13. Schematic diagram showing relationship between knickpoints and channel features.	3-22
Figure 3-14. Downstream end of concrete wall, town of La Honda.	3-24
Figure 3-15. Gabion wall undermined by erosion.	3-24
Figure 3-16. Oversized clasts in gravel bar.	3-25
Figure 4-1. Estimated annual rainfall for La Honda Creek.	4-2
Figure 4-2. Recurrence of annual water year rainfall in La Honda Creek.	4-2
Figure 4-3. Annual deviation from the mean rainfall for La Honda Creek.	4-3
Figure 4-4. Average monthly rainfall totals for La Honda 1952-1977.	4-4
Figure 4-5. Estimated magnitude and frequency of discharge at Delay's bridge.	4-8
Figure 4-6. Photo of downstream face of Delay's bridge looking upstream.	4-9
Figure 4-7. Photo of La Honda Creek channel upstream of Delay's bridge.	4-9
Figure 4-8. Photo of La Honda Creek Channel downstream of Delay's bridge.	4-9
Figure 4-9. Photo of right overbank of La Honda Creek channel upstream of Delay's bridge.	4-9
Figure 4-10. Photo of staff gauge at Delay's bridge.	4-10
Figure 4-11. Cross-section geometry measured at Delay's bridge.	4-11
Figure 4-12. Marsh-McBirney flow meter. USGS bridge board.	4-12

Figure 4-13. Equipment in action, Delay's bridge.	4-12
Figure 4-14. Rating curve showing discharge (cms) versus stage (m) at Delay's bridge.	4-13
Figure 4-15. Hobo Optic StowAway Temperature sensor.....	4-16
Figure 4-16. La Honda Creek water temperatures at Delay's bridge.	4-17
Figure 4-17. Seven-day average air and water temperatures.	4-17
Figure 4-18. The relationship between air and water temperature on La Honda Creek.....	4-18
Figure 4-19. The relationship between stage at Delay's bridge and turbidity.	4-22
Figure 5-1. Cumulative Taxonomic Richness for BMIs.....	5-7
Figure 5-2. Cumulative EPT Taxa for BMIs.	5-7
Figure 5-3. Mean Sensitive EPT Index for BMIs.	5-8
Figure 5-4. Mean Shannon Diversity for BMIs.	5-8
Figure 5-5. Mean Percent Dominant Taxon for BMIs.....	5-9
Figure 5-6. Mean Intolerant Taxa values for BMIs.	5-9
Figure 5-7. Mean Percent Collectors values BMIs.	5-10
Figure 5-8. Mean Percent Filterers values BMIs.	5-10
Figure 5-9. Mean Percent Grazers values BMIs.	5-11
Figure 5-10. Mean Percent Predators values BMIs.	5-11
Figure 5-11. Mean Percent Shredders values BMIs.	5-12
Figure 6-1. Visual estimates of grainsize distribution of the bed of La Honda Creek... 6-4	6-4
Figure 6-2. La Honda Creek longitudinal profile, San Gregorio confluence to Weeks Creek.....	6-5
Figure 6-3. Topographic map of the lower portion of the La Honda Creek watershed. 6-7	6-7
Figure 6-4. Example of three Segment I cross-sections.	6-8
Figure 6-5. Examples of cross-sections in Segment II.	6-9
Figure 6-6. Examples of cross-sections in Segment III.	6-9
Figure 6-7. Volume (m ³) and type of sediment deposits.	6-15
Figure 6-8. Number and type of sediment deposits.	6-16
Figure 6-9. Volumetric contribution of each sample reach to the total volume of measured sediment deposits.....	6-16
Figure 6-10. Sediment deposit volume per unit channel length.	6-17
Figure 6-11. Distribution of estimated age (years) of sediment deposits measured.	6-18
Figure 6-12. Normalized sediment depth of pool deposits, active channel deposits, and bars measured.....	6-19
Figure 6-13. Surface particle size distribution curves.....	6-21
Figure 6-14. Reach average slope versus mean sediment grain size (D ₅₀).	6-22
Figure 6-15. Clast of mudstone from the bed.	6-22
Figure 6-16. An excavated bulk sediment sample site.	6-24
Figure 6-17. Gilson metal sieves used for bulk sediment sampling.	6-24
Figure 6-18. Field sieving in action.	6-24

Figure 6-19. Particle size distribution curves of combined (surface and subsurface) bulk sediment samples.	6-26
Figure 6-20. Comparison of grain size distribution curves of surface pebble counts versus combined bulk sediment samples.	6-28
Figure 6-21. Number and class of pools.	6-30
Figure 6-22. Number of pools in each class.	6-30
Figure 6-23. Number of pools formed or associated with LWD.	6-32
Figure 6-24. Number of pools per residual depth class and their associated cause.	6-32
Figure 6-25. Residual pool depth versus reach average slope.	6-33
Figure 6-26. Number and species of large woody debris (LWD).	6-35
Figure 6-27. Number, position, and form of large woody debris (LWD).	6-36
Figure 6-28. LWD load (m ³ /km).	6-36
Figure 7-1. Badly corroded culvert.	7-2
Figure 7-2. As-built map showing 1955 channel realignment, Sackrete Bend.	7-5
Figure 7-3. Gabion wall failed due to use of inappropriate materials.	7-6
Figure 7-4. Close up of gabion wall.	7-7
Figure 7-5. Effective riprap.	7-7
Figure 7-6. View downstream of Delay's bridge showing encroachment.	7-8
Figure 7-7. Turbid waters flowing into La Honda Creek.	7-11
Figure 7-8. Location map of "pressure points" described in this section.	7-14
Figure 7-9A. Plat map of Landslide Bend pressure point.	7-15
Figure 7-9B. Cross-sections, Landslide Bend pressure point.	7-16
Figure 7-10. Highway 84 at head of Landslide Bend pressure point.	7-17
Figure 7-11. Failing geogrid slope at base of Landslide Bend pressure point.	7-17
Figure 7-12. Downed redwood logs buttressing slope, Landslide Bend pressure point.	7-18
Figure 7-13A. Plat map of Riprap Bend pressure point.	7-19
Figure 7-13B. Cross-sections, Riprap Bend pressure point.	7-20
Figure 7-14. Riprap Bend pressure point. Note slope failure behind riprap.	7-22
Figure 7-15A. Plat map of Sackrete Bend pressure point.	7-24
Figure 7-15B. Cross-sections, Sackrete Bend pressure point.	7-25
Figure 7-16. Sackrete Bend pressure point, view upstream.	7-26
Figure 7-17. Scour at Sackrete Bend pressure point.	7-26
Figure 7-18A. Plat map of Apple Jack's Bend pressure point.	7-28
Figure 7-18B. Cross-sections, Apple Jack's Bend pressure point.	7-29
Figure 7-19. Apple Jack's pressure point showing LWD making up most of the bank.	7-30
Figure 7-20A. Plat map of Green House Bend pressure point.	7-31
Figure 7-20B. Cross-sections, Green House Bend pressure point.	7-32
Figure 7-21. Riprap and fill in bank at Green House Bend pressure point.	7-33
Figure 7-22A. Plat map of 30 mph Bend pressure point.	7-34
Figure 7-22B. Cross-sections, 30 mph Bend pressure point.	7-35
Figure 7-23. View toward Highway 84 at 30mph Bend pressure point.	7-36
Figure 7-24. Measuring bank pin.	7-37

LIST OF TABLES

Table 1-1. Aerial photography, La Honda Creek watershed.....	1-4
Table 2-1. Summary of land management changes and geomorphic processes influencing Highway 84.....	2-7
Table 3-1. Average engineering properties of soils, La Honda area.....	3-8
Table 3-2. Characteristics of soils adjacent to La Honda Creek.....	3-9
Table 3-3. Recurrence intervals for large magnitude earthquakes, San Gregorio fault.....	3-10
Table 3-4. Landslide failure record for rock units, San Mateo County.....	3-14
Table 3-5. Relationship between rock type, number, and styles of landslides.....	3-14
Table 3-6. Total precipitation and number of landslides per year.....	3-15
Table 4-1. Probability of exceedence of annual rainfall, La Honda Creek watershed....	4-3
Table 4-2. Seasonal distribution of rainfall, La Honda 1952-1977.....	4-4
Table 4-3. Estimated depth-duration-frequency of rainfall at La Honda.....	4-6
Table 4-4. Contributing area of each tributary, La Honda Creek watershed.....	4-7
Table 4-5. Regional magnitude-frequency relationships for watersheds in the Bay Area.....	4-7
Table 4-6. Storms during the wet season of WY 2003.....	4-13
Table 4-7. Rating table for discharge versus stage at Delay's bridge.....	4-14
Table 4-8. Temperature ranges for steelhead trout and coho salmon.....	4-16
Table 4-9. Measured turbidity (in NTUs) of water samples collected during high flow events.....	4-19
Table 4-10. Summary of suspended sediment concentration measured in local tributaries or near San Francisco Bay.....	4-21
Table 5-1. Scores for the six biological metrics used to develop the Russian River IBI.....	5-5
Table 5-2. Bioassessment metrics used to describe characteristics of the BMI community.....	5-6
Table 5-3. Trends in diversity and functional feeding groups.....	5-12
Table 5-4. Physical Habitat Scores for Study Reaches within the La Honda Creek watershed.....	5-13
Table 6-1. Salmonid habitat and numbers in La Honda Creek.....	6-3
Table 6-2. Number and age distribution of steelhead and other fish species, La Honda Creek.....	6-4
Table 6-3. Drainage basin area, and bankfull channel width, depth, and cross-sectional area.....	6-10

Table 6-4. La Honda Creek reach average percent slope, standard error and coefficient of variation.	6-11
Table 6-5. Surface grain size data for each sample reach.	6-21
Table 6-6. Bulk sediment sample characteristics.	6-24
Table 6-7. Sieve and square template sizes used for mechanical analysis of bulk gravel samples and pebble count samples.	6-25
Table 6-8. Grain size distribution for bulk sediment samples.	6-27
Table 6-9. Bulk sediment descriptive analysis.	6-27
Table 6-10. DFG Level III and Level IV Habitat Types, 1998.	6-29
Table 6-11. Average pool spacing in La Honda Creek.	6-31

LIST OF PLATES

Plate 1A. Engineering Geological Map of the La Honda Channel, San Mateo County, California (Northern Sheet).	P-1
Plate 1B. Engineering Geological Map of the La Honda Channel, San Mateo County, California (Central Sheet).	P-2
Plate 1C. Engineering Geological Map of the La Honda Channel, San Mateo County, California (Southern Sheet).	P-3
Plate 2A. Historical As Built Map of the La Honda Channel, San Mateo County, California (Northern Sheet).	P-4
Plate 2B. Historical As Built Map of the La Honda Channel, San Mateo County, California (Southern Sheet).	P-5